MEMORANDUM

TO:

Project File

MEMO NO .: WMG-038

931309

FROM:

Bill Gregg/John Craun

FILE: B690-200

SUBJECT: Hickok's Well Survey

DATE: September 21, 1983

We have reviewed the Hickok well survey for the purpose of evaluating our recommendations on multi-aquifer wells. Specifically, Table 5-7 from our report (copy attached) was used to develop a rough cost estimate for multi-aquifer well remedial actions based on the information provided by the Hickok survey.

Information Gaps

The first item in Table 5-7 is to fill information gaps in Hickok's survey. Information that is critical for an effective remedial program for multi-aquifer wells includes obtaining well construction data on at leat two wells that may connect other aquifers with the Mt. Simon aquifer, and on twelve other wells that may connect other aquifers with the Prairie du Chien aquifer. The two deep wells are:

MN unique no. 232727 - 800 ft. deep owned by M.B. Green, and MN unique no. 216104 (W107) - 755 ft. deep, Interior Elevator Co.

Information that we have is that Interior Elevator Company had two wells, one 700 ft. deep and one 970 ft. deep. The existence and condition of these wells should be determined. The twelve other possible multi-aquifer wells identified by Hickok are:

203609	232534
206495	232614
232565	232682
232576	232706
232630	232973
232525	232975

The twelve possible multi-aquifer wells are located as shown in Figure 1. Three additional wells listed by Hickok, which would be possible multi-aquifer wells (216088, 216083, and 216087), were listed as sealed by Hult and Schoenberg (1981).

The well construction for each of these wells needs to be determined. The Hickok survey indicates that these wells penetrate the Prairie du Chien or Jordan formations or that they may be sufficiently deep to do so. The wells should be geophysicalkly logged to determine whether or not they are multi-aquifer wells and whether inter-aquifer flow is occurring.

Another area where more information is needed is for the 18 multi-aquifer wells that were identified by the Hickok survey., Table 1 is a list of these wells and their locations are shown in Figure 2. All of the multi-aquifer wells identified by Hickok connect the basal St. Peter with the Prairie du Chien. It is not known whether inter-aquifer flow occurs in these wells, and if so, whether or not any contaminants in the St. Peter aquifer could migrate into the basal section, and thus be carried down to the Prairie du Chien. Geophysical logging and water quality sampling should provide the necessary data to fill the information gaps for these wells.

The cost estimate for item one in Table 5-7 of our report is \$25,000 to \$50,000. We think this remains as a good estimate for the work to fill information gaps in the Hickok survey.

Items 2 and 3 on Table 5-7 are unaffected by the results of the Hickok survey.

Mt. Simon-Hinckley Multi-Aquifer Wells

Item 4 of Table 5-7 is affected by the results of Hickok's survey in that no new multi-aquifer wells with a connection to the Mt. Simon-Hinckley aquifer were found. If further information on wells 232727 and 216104 (as described earlier) indicates that these wells need to be sealed or reconstructed, then the cost would be \$30,000 to \$60,000 using the cost basis of Table 5-7. Before any remedial work at 232727 would be done, consideration must be given as to whether or not the Prairie du Chien is contaminated at this location. Well 232727 is probably far enough east to be unaffected by any contamination from the site (see Figure 1).

Item 5 was addressed in the earlier discussion of whether or not the multi-aquifer wells identified by Hickok actually transmit contaminants from the basal St. Peter to the Prairie du Chien. Additionally, evaluating ground-water monitoring data and performing simplified modeling should help determine the need for remedial actions for these wells.

Prairie du Chien-Jordan Multi-Aquifer Wells

Item 6 in Table 5-7 recommends reconstructing or sealing the multi-aquifer wells that lead to the Prairie du Chien-Jordan if it is shown that it would be cost-effective. As stated above, Hickok's survey found 18 such wells, all connected with the basal St. Peter. From Figure 2 it is clear that many of these wells are outside the zone of suspected contamination in the St. Peter. At the very most, only seven wells - W45, W46, W48, W49, W62, W66, and SLP7 - are close enough to be affected by any contamination. Hult and Schoenburg (1981) list W66 as "reported filled", so it may not require any further work. In addition, W62 and SLP7 are far enough north that action within the next few decades should not be necessary - if ever. The cost basis for these wells in Table 5-7 is \$15,000 to \$30,000 per well which is probably too high if the wells are to be reconstructed. Depending upon the water needs of the user, a liner could be inserted to seal off the basal St.

Peter, or the Prairie du Chien could be grouted shut. These reconstruction activities would cost much less than \$15,000; a cost of about \$5,000-per well or a total cost of \$20,000 seems more reasonable to reconstruct the four wells in the general area of historic ground—water contamination identified by Hickok that connect the basal St. Peter with the Prairie du Chien.

St. Peter Multi-Aquifer Wells

Item 6 of Table 5-7 also calls for sealing or reconstructing multi-aquifer wells that lead to the St. Peter if this is cost-effective. Hickok's survey identified 26 such wells in St. Louis Park, as shown in Figure 3. An additional 16 St. Peter multi-aquifer wells in Edina and Hopkins are not included in this analysis because of their distance from the site. From Figure 3 it is clear that ony 5 to 8 of these wells are east or southeast of the site and therefore might require remedy, and 3 are probably too far away to require immediate action (nos. 216089, 200538 and 232643). If all of the remaining 5 wells were sealed, the cost would be \$25,000 to \$50,000, using the cost basis of Table 5-7.

MPCA High Priority Wells

In its 1982 Superfund request, the MPCA identified nine high priority multi-aquifer wells for abandonment, five extending to the Prairie du Chien (W35, W40, W45, W46, and W62) and four to the St. Peter or basal St. Peter (W29, W41, W44 and W75). Our review of Hickok's survey resulted in three of the Prairie du Chien wells (W45, W46 and W62) and two St. Peter wells (W44 and W75) being identified, leaving two wells in each category unaccounted for.

Cost Implications

Table 2 summarizes the implications of this review of Hickok's well survey on the extent and costs of multi-aquifer well remedial actions. Comparision with Table 5-7 from our report (copy attached) shows that the revised estimate of Table 2 generally falls in the lower half of our original estimate. This reflects the smaller number of multi-aquifer wells actually discovered compared to our worst case assumptions. Because of the more rapid transport of two-ring PAH in the shallow aquifers (Drift-Platteville and St. Peter) than we originally assumed (see J. Craun's memo of September 21), the future work items and expenditures will probably be required every 25 years or so and not as infrequently as every 50 years. This puts our total present value cost estimate for multi-aquifer well remedial action in the range of \$0.1 to \$0.6 million, compared to our original estimate of \$0.1 to \$0.9 million, plus up to \$0.7 million in contingency actions (which are now included in our \$0.1 to \$0.6 million cost estimate) (Tables 7-1 and 7-2 of our report).

It should be noted that the cost estimates in Table 2 are based on reconstructuring wells so they can still be used or sealing them and replacing the user's water supply with city water. No costs are included for drilling new wells, since this extra expense would be avoided if possible.

TABLE 5-7

ESTIMATED COSTS OF RECOMMENDED

REMEDIAL ACTIONS FOR OFF-SITE MULTI-AQUIFER WELLS

Recommended Remedial Action	Currenc Expenditures	Fixed Expenditures (made every 25 to 50 years)
1. Fill Information Gaps in Rickok's Recent Multi- aquifer Well Survey	\$25,000 - \$50,000	Not Applicable
2. Repeat Multi-aquifer Well Inventory for Shallow Aquifer as Contaminants Migrate	Noc Applicable	\$25,000 - \$100,000
 Expand Inventory of Multi- aquifer Wells Connecting the Prairie du Chiem-Jordan to the Mt. Simon-Rinckley 	\$20,000 - \$50,000	\$20,000 - \$50,000
4. Seal or Reconstruct Multi- aquifer Wells which Connect:	•	
 Shellow Aquifers to the Mt. Simon-Hinckley 	\$0 - \$300,000(#)	\$0 - \$360,000(a)
 Prairie du Chien-Jordan to the Mt. Simon-Minckley 	\$0 - \$150,000(h)	\$0 - \$150,000 ^(b)
5. Assess the Significance of Multi-equifer Wells Identified in Item 6	\$25,000(*)	\$25,000(e)
6. If Shown to be Cost-Effective as a Result of Item 5 - Seal or Reconstruct Multi-aquifer Wells which Connect:		
 Drift-Platteville to the St. Peter 	\$0 - \$200,000(c)-	\$0 - \$200,000(c)
 Drift-Platteville and/or St. Peter to the Prairie du Chien-Jordan 	\$0 - \$300,000(a)	\$0 - \$300,200(4)
Total Present Value Cont • Without Item 6 • With Item 6	\$70,000 - \$575,000 \$70,000 - \$1,075,000	Every 25 Years \$30,000 - \$260,000 \$30,000 - \$470,000 \$6,000 - \$105,000

Notes

- (a) Based on zero to ten wells being sealed at a cost of \$15,000 to \$30,000 per well (see Table 5-6).
- (b) Based on zero to five wells being sealed at a cost of \$15,000 to \$30,000 per well (see Table 5-6).
- (c) Based on zero to twenty wells being sealed at a cost of \$5,000 to \$10,000 per well (see Table 5-6).
- (d) Based on zero to ten walls sealed at a cost of \$15,000 to \$30,000 per well (see Table 5-6).
- (e) Study costs for evaluating ground-water monitoring data and for performing simplified ground-water modeling.

TABLE 1
MULTI-AQUIFER WELLS IDENTIFIED BY HICKOK SURVEY

Well No.	MN Unique		log	Casing
NON-RESPONSIVE 107-272 Osp 272-280 Opc 4" csg 272-280 Opc 201-244 Osp 272-280 Opc 201-244 Osp 244-277 Opc 0-232 170-233 Osp 244-277 Opc 0-232 170-233 Osp 25" csg 0-192 233-236 Opc 0-192 233-236 Opc 0-192 233-236 Opc 0-194 243-303 Opc 0-223 243-206 Opc 0-220 0pc 0-240 0pc 0-241 0pc 0-225 0pc 0-234 0pc 0-225 0pc 0-234 0pc 0-23				0.245
200544 272-280 Opc 4" csg 201-244 Osp 244-277 Opc 0-232 201057 201057 278-243 Osp 233-236 Opc 0-192 201062 78-243 Osp 243-303 Opc 0-194 201063 29-250 Osp 0-194 201065 94-250 Osp 0-223 201065 92-167 Osp 167-168 Opc 0-98 206419 201-290 Opc 53-177 206429 100-266 Osp 266-270 Opc 0-220 206430 100-260 Osp 270-271 Opc. 0-223 206436 100-260 Osp 260-380 Opc 0-220 206436 206436 206-270 Opc 0-223 206436 206436 206-270 Opc 0-223 206436 206436 206-270 Opc 0-224 206437 206438 270-271 Opc. 0-247 206438 206-380 Opc 0-247 206445 20645 206-380 Opc 0-247 206445 20645 206-380 Opc 0-247 206445 20645 206-380 Opc 0-246 20645 20645 206-380 Opc 0-247 206489 122-265 Osp 0-244 206489 206-250 Osp 260-381 Opc 0-241 206489 226-381 Opc 0-241 206489 226-381 Opc 0-225 206489 226-381 Opc 0-225		NON-RESPONSIVE	107-272 Osp	
201-243 osp	114302		272-280 Opc	4 (36
200544 201057 201057 201062 78-243 Osp			201_244 Osp	
201057 201062 78-243 Osp	200544			0-232
201057 233-236 Opc 233-236 Opc 333-236 Opc 39-243 Osp 243-303 Opc 243-303 Opc 201063 250-292 Opc 250-292 Opc 250-292 Opc 201065 206419 206429 206429 206429 206430 206445 206450	2000			- **
201062 78-243 Osp 243-303 Opc 78-243 Osp 243-303 Opc 94-250 Osp 250-292 Opc 201063 201065 201065 201065 201069			170-233 Osp	
201062 243-303 Opc 243-303 Opc 34-250 Osp 250-292 Opc 250-292 Opc 201065 2010665 201067 2010	201057			0+135
201062 243-303 Opc 243-303 Opc 34-250 Osp 250-292 Opc 250-292 Opc 201065 2010665 201067 2010				8" csg
201062 243-303 Ope 94-250 Osp 250-292 Opc 92-167 Osp 167-168 Opc 92-167 Osp 167-168 Opc 72-201 Osp 201-290 Opc 100-266 Osp 266-270 Opc 100-266 Osp 270-271 Opc 206430 100-260 Osp 270-271 Opc 100-260 Osp 260-380 Opc 206438 W62 105-274 Osp 274-394 Opc 107 206438 W62 10645 107 20645 108-260 Osp 274-394 Opc 109-246 122-265 Osp 260-381 Opc 188-250 Osp 250-253 Opc 192-265 Osp 256-284 Opc 122-265 Osp 256-284 Opc 122-265 Osp 256-284 Opc 122-265 Osp 260-331 Opc 188-250 Osp 256-284 Opc 122-265 Osp 260-331 Opc 188-250 Osp 256-284 Opc 122-265 Osp 265-312 Opc 122-265 Osp 265-312 Opc 0-234	, , , , , , , , , , , , , , , , , , , ,			
201063 250-292 Opc 92-167 Osp 167-168 Opc 72-201 Osp 201-290 Opc 72-201 Osp 201-290 Opc 100-266 Osp 266-270 Opc 100-266 Osp 266-270 Opc 101-270 Osp 270-271 Opc 100-260 Osp 260-380 Opc 100-260 Osp 260-380 Opc 100-260 Osp 260-380 Opc 100-260 Osp 260-380 Opc 100-260 Osp 274-394 Opc 100-260 100-260 Osp 260-380 Opc 100-260 100-260 Osp 260-380 Opc 100-247 105-274 Osp 274-394 Opc 107 206438 122-265 Osp 260-381 Opc 188-250 Osp 260-381 Opc 188-250 Osp 260-381 Opc 188-250 Osp 260-253 Opc 206489 122-265 Osp 260-250 Osp 260-260 Osp 260-260 Osp 260-260 Osp 260-381 Opc 188-250 Osp 260-381 Opc 0-241	201062		243-303 Opc	•
201063 250-292 Opc 92-167 Osp 167-168 Opc 0-98 72-201 Osp 201-290 Opc 53-177 100-266 Osp 266-270 Opc 101-270 Osp 270-271 Opc 0-223 206430 100-260 Osp 270-271 Opc 0-223 206436 100-260 Osp 260-380 Opc 100-247 SLP 7 206438 206436 206436 212-265 Osp 206445 W45 206450 W45 206450 W49 206487 206489 188-250 Osp 260-284 206489 122-265 Osp 260-284 206489	·		04-250 Osp	
201065 201065 201065 201065 2010619 2010619 2010619 2010619 2010619 2010629 2010629 2010629 2010629 2010629 2010020	201.063			0-223
201065 167-168 Opc 72-201 Osp 201-290 Opc 100-266 Osp 266-270 Opc 206429 101-270 Osp 270-271 Opc 100-260 Osp 270-271 Opc 100-260 Osp 260-380 Opc 100-260 Osp 260-380 Opc 105-274 Osp 274-394 Opc 105-274 Osp 274-394 Opc 102-265 Osp 265-312 Opc 206450 W49 206487 206489 188-250 Osp 256-284 Opc 122-265 Osp 266-284 Opc 122-265 Osp 265-312 Opc 4" 0-241 206489 122-265 Osp 265-312 Opc 4" 0-225 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-241	2020-		230-272 040	
201065 206419 206429 206429 206430 206430 206436 SLP 7 206438 W62 206445 W62 206450 W45 206450 W45 206489 206489 206489 216065 20720 206489 206429 206429 206429 206429 206429 20020 200			92-167 Osp	
206419 201-290 Opc 100-266 Osp 266-270 Opc 101-270 Osp 266-270 Opc 101-270 Osp 270-271 Opc. 206436 206436 206-380 Opc 100-260 Osp 260-380 Opc 100-247 206438 206445 206445 206445 206450 206450 206450 206487 206489 206489 216065 2122-265 Osp 250-284 Opc 224-256 Osp 256-284 Opc 122-265 Osp 256-284 Opc 122-265 Osp 256-284 Opc 122-265 Osp 266-284 Opc 0-234	201065			0-98
206419 201-290 Opc 100-266 Osp 266-270 Opc 101-270 Osp 266-270 Opc 101-270 Osp 270-271 Opc. 206436 206436 206-380 Opc 100-260 Osp 260-380 Opc 100-247 206438 206445 206445 206445 206450 206450 206450 206487 206489 206489 216065 2122-265 Osp 250-284 Opc 224-256 Osp 256-284 Opc 122-265 Osp 256-284 Opc 122-265 Osp 256-284 Opc 122-265 Osp 266-284 Opc 0-234				£" ==0
206429 206429 100-266 Osp				
206429 206430 206430 206436 206436 SLP 7 206438 W62 206445 W45 206450 W49 206487 206489 206489 206489 2066-270 Opc 101-270 Osp 270-271 Opc. 100-260 Osp 260-380 Opc 100-260 Osp 260-380 Opc 100-247 100-247 100-260 Osp 260-380 Opc 100-247 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-260 Osp 260-381 Opc 100-241 100-225 100-225 100-225 112-265 Osp 265-312 Opc	206419		201-290 Opc	33 2
206429 206430 206430 206436 206436 SLP 7 206438 W62 206445 W45 206450 W49 206487 206489 206489 206489 2066-270 Opc 101-270 Osp 270-271 Opc. 100-260 Osp 260-380 Opc 100-260 Osp 260-380 Opc 100-247 100-247 100-260 Osp 260-380 Opc 100-247 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-241 100-260 Osp 260-381 Opc 100-241 100-225 100-225 100-225 112-265 Osp 265-312 Opc			100 066 000	4" csg
206430 101-270 Osp 270-271 Opc. 100-260 Osp 260-380 Opc 20" 0-247 105-274 Osp 274-394 Opc 105-274 Osp 90-246 W62 122-265 Osp 265-312 Opc 188-250 Osp 260-381 Opc 206487 206489 188-250 Osp 250-253 Opc 206489 122-265 Osp 250-253 Opc 260-381	206/29			0-220
206430 206436 206436 206438 206438 206438 206445 206445 206450 206450 206487 206489	200427		266-270 Opc	
206430 270-271 Opc. 100-260 Osp 260-380 Opc 100-247 105-274 Osp 274-394 Opc 102-265 Osp 265-312 Opc 206450 206450 206450 206487 206489 206489 206489 274-256 Osp 250-253 Opc 224-256 Osp 250-253 Opc 224-256 Osp 255-312 Opc 2255-312 Opc 2265-312 Opc			101-270 Osp	
206436 SLP 7 206438 W62 206445 W45 206450 W49 206487 206489 100-260 Osp 260-380 Opc 10" 105-274 Osp 274-394 Opc 122-265 Osp 265-312 Opc 4" 205-312 Opc 188-250 Osp 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 4" 206489 122-265 Osp 256-284 Opc 122-265 Osp 265-312 Opc 0-234	206430			0-223
206436 SLP 7 206438 W62 206445 W45 206450 W49 206487 206489 100-260 Osp 260-380 Opc 10" 105-274 Osp 274-394 Opc 122-265 Osp 265-312 Opc 4" 206489 188-250 Osp 256-284 Opc 122-265 Osp 260-381 Opc 4" 206489 188-250 Osp 256-284 Opc 122-265 Osp 266-381 Opc 4" 206489 122-265 Osp 266-381 Opc 4" 206489				20"
206436 SLP 7 206438			100-260 Osp	
206438 W62 206445 W45 206450 W49 206487 206489 105-274 Osp 274-394 Opc 90-246 122-265 Osp 265-312 Opc 96-260 Osp 260-381 Opc 188-250 Osp 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-27 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-234			260-380 Opc	
206438 w62 206445 w45 206450 w49 206487 206489 274-394 Opc 90-240 122-265 Osp 265-312 Opc 96-260 Osp 260-381 Opc 4" 250-253 Opc 224-256 Osp 250-253 Opc 4" 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-234	SLP /		205 276 OFD	10"
206445 W45 206450 W49 206487 206489 122-265 Osp 265-312 Opc 96-260 Osp 260-381 Opc 188-250 Osp 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-241 4" 0-27 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-234	206438		105-274 Osp	90-246
206445 W45 206450 W49 206487 206489 122-265 Osp 265-312 Opc 96-260 Osp 260-381 Opc 4" 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 122-265 Osp 265-312 Opc 6" 0-234			2/4-334 000	
206445 W45 206450 W49 206487 206489 265-312 Opc 96-260 Osp 260-381 Opc 4" 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-234	,,,,		122 – 265 Osp	
206450 W49 206487 206487 206489 206489 96-260 Osp 260-381 Opc 4" 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 6" 0-241 4" 0-241 4" 0-27	206445			0-244
206450 W49 206487 206489 20	W45			6"
206450 W49 206487 206487 206489 216065 260-381 Opc 4" 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 0-234				
206487 206489 188-250 Osp 250-253 Opc 224-256 Osp 256-284 Opc 122-265 Osp 265-312 Opc 4" 0-27			260-381 Opc	• -
206487 250-253 Opc 224-256 Osp 256-284 Opc 216065 216065 250-253 Opc 4" 0-225 122-265 Osp 265-312 Opc 0-234	W49		100 350 Den	411
224-256 Osp 4" 226-284 Opc 0-225 122-265 Osp 6" 216065 265-312 Opc 0-234	206487		250-253 One	0-27
206489 256-284 Opc 0-225 216065 122-265 Osp 6" 265-312 Opc 0-234	200407		510-522 Ab-	- 44
206489 256-284 Opc 0-223 122-265 Osp 6" 216065 265-312 Opc 0-234			224-256 Osp	
122-265 Osp 6" 216065 265-312 Opc 0-234	206489			0-225
216065 122-265 0sp 265-312 Opc 0-234	,			۲۱ د ا
265-312 Ope			_	-
W46	216065		265-312 Opc	0-234
•• •	W46		· .	

TABLE 1 (continued)

MN Unique Well No.	Location	Log	Casing
216067	NON-RESPONSIVE	94-257 Osp	20"
W48		257-377 Opc	0 – 255
216081	Camb. & M'haha.Cr.	87-251 Osp	6"
W66		251-280 Opc	0 - 212

REVISED ESTIMATE OF COSTS FOR MULTI-AQUIFER WELL REMEDIAL ACTIONS


(thousands of dollars)

Item No. (see Table 5-7 for explanation)	Current Expenditures	Future Expenditures (Once every 25 years)
1	25-50	NA
2	NA (a)	25-100
3	20-50	20–50
. 4	0-60 ^(b)	0-150 ^(c)
5	25	25
6	0-150	0-250 ^(e)
	70–335	30–240


Notes:

- (a) NA = not applicable.
- (b) Based on 0 to 2 wells requiring action (see page 2), at a cost of \$15,000 to \$30.000 per well.
- (c) Based on 0 to 5 wells requiring action at \$15,000 to \$30,000 each. This number of wells is lower than the original estimate of 0 to 15 wells based on projecting the results of Hickok's well survey.
- (d) Based on up to 4 wells requiring action at \$5,000 each (see page 3) plus 2 additional wells identified by the MPCA at up to \$30,000 each (see page 3), for wells leading to the Prairie du Chien, and for up to 7 wells leading to the St. Peter (see page 3) at up to \$10,000 each.
- (e) Based on 0-10 St. Peter wells at \$5,000 to \$10,000 each and 0-5 Prairie du Chien wells at \$15,000 to \$30,000 each. These numbers of wells are lower than our original estimates (see Table 5-7) based on the results of Hickok's well survey.

FIGURE 1. POSSIBLE MULTI-AQUIFER WELLS (Log and/or Casing Schedule Not Known)




Note: All numbers preceded by 232 unless marked otherwise (depth or aquifer if reported)



Note: All wells connect the basal St. Peter with the Praire du Chien

FIGURE 3. ST. PETER MULTI-AQUIFER WELLS IDENTIFIED BY HICKOK'S SURVEY



Note: All wells connect the Drift-Plateville with the St. Peter.